

Participant:

Competition Inspection Cnecklist						
Inspecti	on Type:	Initial	_ Mandated	Random		
Size 1	Inspection					
	bot fits within starting size rasured WITH Robot, Reoff			lls or ceiling of the sizing box! Ro	bot should be	
Overa	all Inspection					
Tea	Team Number is visible from two sides has been built using the Open Program License Plate Template.					
Ro	Robot does NOT contain any components which will be intentionally detached on the playing field.					
Ro	Robot does NOT contain any components that could damage the playing field.					
Ro	Robot does NOT contain any sharp edges or corners.					
Ro	Robot poses NO obvious unnecessary risk of entanglement.					
Tea	Team is only competing with ONE robot - they have no spare or replacement robots.					
Red	Reoff lights must be installed on both sides of bot, free from obstructions and easily seen from all four sides.					
	The Ethernet port is mounted so that the field Ethernet cord can be plugged directly into the port when the robot is on the field in its normal starting position.					
An	Any grease is used only in moderation on components that do not contact the field, objects, or other robots.					
Parts	Inspection					
Ro	Robot uses a maximum of three (3) of these approved batteries:					
Т	Tenergy NiMH 9.6V 2000mAh Batter	y Item No. 11401-01		00mAh Flat Battery Pack Item No. 11328		
	Tenergy NiMH 7.2V Flat Battery Pack			00 mAh battery Item No. 11408		
	Venom NiMH 9.6V 3000mAh battery			0mAh battery Model 1546-8		
	Venom NiMH 9.6V 5000mAh battery			ery NiMH – Discontinued		
	VEX 7.2V Robot Battery NiMH 2000		VEX 7.2V ROBOL Battery	y NiMH 2000mAh P/N: 276-1456		
Bat 1. 2.	Battery chargers are limited to the following: 1. Tenergy Universal Smart Charger for HiMH/NiCd Battery Packs (6V – 12V) Item No. 01025 2. Vex 7.2V Smart Chargers 276-1445, 276-2519, 276-2221, 276-2235					
this	HIGHLY RECOMMENDED Circuit A has a battery attached and is used ONLY to power the control unit and sensors. I this recommendation is not followed a team representative must initial the box to left and state they understand they are greatly increasing the likelihood that they will have a match affecting, on field power failure.					
A r	A maximum of 2 pneumatic tanks have been used in the robot					
Tot	Total number of servos and motors is not greater than ten (10) or twelve (12) if pneumatics are not used.					
Pne	Pneumatics have not been modified in any way.					
The	The Reoff has not been modified in any way					
No	No rare earth magnets or electromagnets, other than those used in shielded motors, have been used.					
No	No part, or set of parts, that inhibits the normal operation and/or communication of other robots, has been used.					
No	No power sources other than pneumatics, batteries or compression (rubber bands, springs, etc.) have been used.					
OTC	Inspection					
Reoff is installed and functions properly and its LED strips are clearly visible.						
Reason for Failure (if any):						
I hereby followed		e is true, and to the best	of my knowledge	e all rules and regulations have	been	

Inspector: